







1. Н14, h14, ±t2/2.
2. *Размеры для справок.
3. Сварные швы по ГОСТ 14771-76 в среде аргона.
4. Сварные швы проверить на герметичность.
5. Приварку заглушек змеевика поз.23 см.лист 3.


						ВДП-1.100 СБ					
						Корпус Сборочный чертёж	Лит.		Масса	Масштаб	
Изм.	Лист	№ докум.	Подп.	Дата				255.99	1:5		
Разраб.		Шукшаев									
Пров.											
Т. контр.											
							Лист 1		Листов 4		
Н. контр.											
Утв.											
Шифр:						Копировал				Формат А2	

Име. № подл.	Подп. и дата	Взам. инв. №	Име. № дубл.	Подп. и дата	Справ. №	Перв. примен.


В-В



Г-Г (1 : 10)



Д (1 : 2)



Име, № подл.	Подп. и дата	Име, № дубл.	Подп. и дата
Име, № подл.	Подп. и дата	Име, № дубл.	Подп. и дата

Изм.	Лист	№ докум.	Подп.	Дата

Шифр:

Копировал

Формат А2

ВДП-1.100 СБ

Лист
2

Файл ВДП-1.100 СБ - Корпус

This diagram illustrates the assembly of a round dining table. The main components shown are the glass top, the metal frame (labeled 23), and the base with four legs. The assembly process involves securing the frame to the base and attaching the glass top. Various hardware items like screws, bolts, and washers are shown in their respective positions for assembly. Callout '2' points to a screw on the top edge, and callout '23' points to the metal frame slats.

